Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 12/9/2014	Man Days: 1
Inspection Unit: Springfield	
Location of Audit: Springfield	
Exit Meeting Contact: John Sigler	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Kevin Hecker	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION			
Location of Construction:		Construction P	erformed By:
3600 block of West Wabash Avenue, Sprin	gfield, IL	KSE Construction	on (contracted by Ameren Illinois)
Contractor Foreman:			
Operator Inspector:			
	Person(s	s) On Job Site	
Mike Maxheimer	John Sigler		John Kelly
Dallas Jett	Rick Br	iener (K&S)	John Borden (K&S)
Bill North (K&S)		-	-
-		-	-

Description of Construction:

Ameren Illinois was installing a new 10 3/4" welded steel line serving the south west side of Springfield along West Wabash Avenue. This project was in anticipation of a road widening project between Koke Mill Road and Mercantile Drive.

MAIN INSTALLATION		Status
[192.55]	Steel	Yes
[192.59]	PE	No
[192.59]	Other	No
[192.5]	Class location :	Class 3
[192.619,192.621,192.623]	MAOP	110 psig
[192.63]	Pipe Size :	10.75"
[192.55,192.59]	Specification :	API 5L

AMEREN ILLINOIS COMPANY/12-9-2014

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Manufacturer :	TMK IPSCO
[192.55,192.59]	Pipe Grade :	X-52M
[192.55,192.59]	Wall Thickness :	.365"
[192.63(a)(2)]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
[192.227]	Date of Welder qualification:	7/29/14
[192.227]	Welder's Name:	John Borden
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Satisfactory
General Comment:		
8010 on hot pass (5/32") and cap pass (3/16") welds. F	2003. Staff observed a 30-degree bevel on pipe ends. Welder utilized 6010 rod or Pipe was preheated and temperature checked with a Milwaukee laser temperature to clamp was repositioned/removed. No deficiencies were discovered.	
[192.285]	Date of Plastic Joining Qualification :	Not Applicable
General Comment:		
No plastic joining was observed as part of this inspection	n.	
[192.285]	Joiner's name:	Not Applicable
General Comment:		
No plastic joining was observed as part of this inspectio	n.	
[192.455]	Is buried metallic pipe coated?	Satisfactory
General Comment:		
Staff observed Bill North apply Denso Protal 7125 coating	ng which is a fast cure, low temperature coating.	
[192.461]	Does coating meet 192.461?	Satisfactory
General Comment:		
Staff observed Bill North apply Denso Protal 7125 coating	ng which is a fast cure, low temperature coating.	
[192.455(a)(1)]	Is cathodic protection being provided?	Satisfactory
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	Yes
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Checked
General Comment:		
Staff did not observe pipe being installed in the ditch. A	portion was to be bored in, with the rest open cut.	
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Satisfactory
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
No above-ground facilities were inspecte	d as part of this audit.	
[192.303]	Are comprehensive written construction specifications available and adhered to?	Satisfactory
General Comment:	·	
Construction plans were available to Ame	eren/K&S staff on the job site.	
[192.305]	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
General Comment:		
A welding instructor/inspector for Amerei	n was on site to observe and inspect welds.	
[192.307]	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?	Satisfactory
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Not Applicable
General Comment:		
Back-filling was not observed during this	audit.	
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Not Applicable
General Comment:	·	
No plastic pipe was included in this inspe	ection.	
[192.321(e)]	Does plastic pipe have means of locating while underground?	Not Applicable
General Comment:		
No plastic pipe was included in this inspe	ection.	
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
[192.327]	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory
General Comment:		
	be maintained to accommodate the drainage system from the road expansion project. Staff was erved as it was being installed in the ditch/bored into the ground.	s on-site to observe
[192.503]	Are general testing requirements being met?	Not Applicable
General Comment:		
No testing was observed as part of this in	nspection.	
[192.517]	Are records being made of strength and leak tests?	Not Applicable
General Comment:	· · · · · · · · · · · · · · · · · · ·	
No testing was observed as part of this in	nspection.	

AMEREN ILLINOIS COMPANY/12-9-2014

Page 3 of 5

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Were non-qualified personnel being directed and observed by a qualified individual? Dersonnel was qualified for tasks being performed.	Not Applicable
personnel was qualified for tasks being performed.	
personnel was qualified for tasks being performed.	
Were span of control limitations being followed?	Not Applicable
<u> </u>	
sks performed.	
	No
Were One Call Notifications performed as required?	Satisfactory
Dig Ticket #	-
<u> </u>	
Are adequate steps taken to minimize the potential for accidental ignition?	Not Applicable
<u> </u>	
nosphere was present during this inspection.	
Was each repair made by welding to a transmission line made in accordance with 192.713, 192.715, and 192.717 and examined in accordance with 192.241?	Not Applicable
-pressure distribution line, not transmission.	
	Were One Call Notifications performed as required? Dig Ticket # Are adequate steps taken to minimize the potential for accidental ignition? Mosphere was present during this inspection. Was each repair made by welding to a transmission line made in accordance with 192.713, 192.715, and 192.717 and

MAIN INSTALLATION CHECKLIST

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.